



FIG. 1



2/14

FIG. 2



3/14

FIG. 3 Z




FIG. 4A

SENSITIVITY LIMIT OF X,Y,Z DIRECTIONS (mm)





FIG. 4B



4/14

FIG. 5






FIG. 6
SENSITIVITY
LIMIT




5/14

FIG. 7




6/14

FIG. 8



7/14

FIG. 9



8/14

FIG. 10






FIG. 11



10/14

FIG. 12



11/14

FIG. 13






FIG. 14






13/14

FIG. 15



14/14

FIG. 16

AYOUT OF BUTTONS	AVE. OF OPERA- TION TIME	SUBJECTIVE EVALUATION
①	46.4sec 	0
②	43.2sec 	6
③	43.2sec 	9